



December 15, 2014

ADDENDUM #1
IFB #15-55
Concrete Repairs at Downes Parking Garage

The number of this Addendum, Addendum No. 1, must be entered in the space provided on the Bid Form, for each of the four bids.

CLARIFY:

1. In reference to the 33 capstone that are reset and anchored can you tell me the size of 1 cap stone?
 - a. Cut and pasted from spec... Form and pour new 8" thick, 18" wide and 58" long capstone with new rebar reinforcing.
2. where we are cutting and caulking the transverse and bed joints can you provide approximate linear feet of joint and what we are cutting and removing?
 - a. Base approximate linear footage on the above dimensions.
3. Where the Freeze damaged CMU are to be replaced can you provide a square footage to be removed and replaced
 - a. Less than 10 sq. ft. (2-3 CMU blocks)

Sincerely

P. Michael Vaughn
Chief Procurement Officer