



Review of Utility Company Request for New Conduit/Pole Location

Applicant Information

Project Address

Utility
(Select one) Gas

Harvard, Stevens, Troy & Nicolett Streets

Reason

The existing gas pipe in these streets is prone to leaking and needs to be replaced.

Date Submitted 2/12/2024

Review done by Joseph Cady

Sidewalk Material Asphalt

Note: Sidewalk material to be replaced in kind (Concrete in full panels only)

Are Sidewalk Vaults present? YES NO

Is Work on Street under a Paving Moratorium? YES NO

Is this location within the Flood Plain? YES NO


Are ADA requirements being met? YES NO

Comments


A portion of the project on Steens St south of Westford St is under moratorium. Westford St south of Stevens St will need to be milled and paved curb to curb as part of this project.

Outcome of Review


Recommended



Recommended With
Comments



Not Recommended



Ting Chang, P.E.
City Engineer