



## Review of Utility Company Request for New Conduit/Pole Location

Applicant Information

Project Address

Utility  
(Select one) Electric

78-80 Middlesex St

Reason Electrical service needs to be upgrade to provide new service to the redevelopment of 78-80 Middlesex St

Date Submitted 3/4/2024

Review done by Joseph Cady

Sidewalk Material Concrete

**Note: Sidewalk material to be replaced in kind (Concrete in full panels only)**

Are Sidewalk Vaults present? YES  NO

Is Work on Street under a Paving Moratorium? YES  NO

Is this location within the Flood Plain? YES  NO

Are ADA requirements being met? YES  NO

### Comments

There may be private sidewalks vaults near some of the proposed conduit location that will need to be considered. Contractor to verify vault location prior to construction.

### Outcome of Review

Recommended

Recommended With  
Comments

Not Recommended

Ting Chang, P.E.  
City Engineer