

## Review of Utility Company Request for New Conduit/Pole Location

Applicant Information

Project Address

Utility  
(Select one) **Gas**

Appleton St from South St to Gorham St

Reason The existing 6 inch cast iron pipe is a leak prone pipe, they are proposing to replace it with a 2-inch high pressure plastic pipe

Date Submitted 7/21/2024

Review done by Joseph Cady

Sidewalk Material **Asphalt**

**Note: Sidewalk material to be replaced in kind (Concrete in full panels only)**

Are Sidewalk Vaults present? YES  NO

Is Work on Street under a Paving Moratorium? YES  NO

Is this location within the Flood Plain? YES  NO


Are ADA requirements being met? YES  NO

Comments


No comment

Outcome of Review


Recommended



Recommended With  
Comments



Not Recommended



Ting Chang, P.E.  
City Engineer